

AGENDA

TEXAS TRANSPORTATION COMMISSION 125 East 11th Street Austin, Texas

THURSDAY May 26, 2022

NOTE:

Persons with special needs or disabilities who require auxiliary aids or services are requested to contact Nicole Lawson at (512) 936-0908 at least three working days before the day of the meeting so that appropriate arrangements can be made.

Atención. Si desea recibir asistencia gratuita para traducir esta información, llame al 512-305-9500.

10:00 A.M. CONVENE MEETING

1. Safety Briefing

Staff will provide general safety instruction.

2. **Opening Comments from Commissioners and Executive Director**

3. **Consider the approval of the Minutes** of the April 19, 2022, special meeting and the April 20, 2022, regular meeting of the Texas Transportation Commission

4. Acknowledgment of Service Recognize by resolution Chief Engineer William L. Hale, P.E., for 39 years of service to the department

5. **GRIT Award** (Presentation)

6. Contracts

Consider the award or rejection of contracts for highway construction and maintenance, and construction and rehabilitation of buildings (Presentation) *These proposed minute orders contain information concerning the receipt of bids for highway improvement contracts. The department may reschedule receipt of bids for those projects where the commission rejects all bids. Those bids accepted by the commission will result in conditional contract awards to the low bidders. Contract award conditions may involve securing funding from other sources, the contractor's ability to satisfy federal DBE subcontracting requirements, or other requirements as outlined in the project bid proposal.*

a. **Highway Improvement and Other Transportation Facilities** (see attached itemized list) (MO)

b. **Routine Maintenance** (see attached itemized list) (MO)

7. **Discussion Items**

- a. Cash Management and Contract Awards (Presentation)
- b. **Legislative Appropriations Request** (Presentation) Discussion regarding the development of the Texas Department of Transportation's Fiscal Year 2024-2025 Legislative Appropriations Request (LAR). Staff will discuss the development of the LAR with the commission and seek direction on components of the LAR.
- c. North Houston Highway Improvement Project (Presentation) Staff will provide an update on the status of the North Houston Highway Improvement Project including any progress toward resolution with FHWA and Harris County.

8. Strategic Plan

Consider the adoption of the 2023-2027 Strategic Plan for submission to the Legislative Budget Board and the Office of the Governor (MO) (Presentation)

The department's 2023-2027 Strategic Plan provides the mission, goals, action plans, and budget structure (objectives, strategies, and budgetary performance measures) that will direct the department over the next five years. In addition to these core components, the plan includes all of the supplemental components required by the Legislative Budget Board and the Office of the Governor, such as the Historically Underutilized Business (HUB) plan, capital improvement plan, workforce plan, customer service report, and an identification of redundancies and impediments. Upon commission approval, department staff will finalize the plan package according to the instructions provided by the Legislative Budget Board and the Office of the Governor for official submission of the plan to those entities by the June 1, 2022 deadline.

9. Annual Highway Safety Plan

Consider approval of funding for the 2023 Highway Safety Plan (MO) (Presentation) The department develops and implements an annual Highway Safety Plan (HSP). Federal funds are allocated by the National Highway Traffic Safety Administration and are used for traffic safety grants identified in the HSP. The HSP organizes anticipated grants into focus-oriented program areas. This minute order lists the number of grants in each program area and the allocated amounts for FY 2023.

10. State Infrastructure Bank (Presentation)

- a. **Williamson County** Round Rock Transportation and Economic Development Corporation - Consider preliminary approval of a request from the Round Rock Transportation and Economic Development Corporation for a State Infrastructure Bank loan in the amount of up to \$27,000,000 to pay for the costs of utility relocation, right-ofway acquisition and construction necessary for a non-tolled, off-system project involving various improvements to Gattis School Road in Williamson County, Texas (MO) *Round Rock Transportation and Economic Development Corporation (Round Rock TEDC) will secure the loan with a pledge of sales tax revenue. The loan will be used to pay Round Rock TEDC's costs associated with utility relocation, right-of-way acquisition and construction necessary for a non-tolled, off-system project involving various improvements to Gattis School Road in Williamson County, Texas.*
- b. **Zapata County** Falcon Rural Water Supply Corporation Consider final approval of a request from the Falcon Rural Water Supply Corporation for a State Infrastructure Bank loan in the amount of up to \$786,000 to pay for the costs of utility relocation necessary for a non-tolled state highway improvement project to widen US 83 in Zapata County, Texas (MO)

Falcon Rural Water Supply Corporation (WSC) will secure the loan with a pledge of water revenues. The loan will be used to pay the WSC's costs associated with utility relocation necessary for a non-tolled state highway improvement project to US 83 in Zapata County, Texas.

11. Real Estate Disposition

Chambers County - FM 3180 - Consider the removal from the system, transfer of jurisdiction, control, and maintenance, and transfer of right of way to the City of Mont Belvieu, Texas (MO) *The district has determined that a segment of roadway is no longer needed as part of the system. The City of Mont Belvieu (city) has agreed to assume jurisdiction, control, and maintenance and has requested that the right of way be transferred to the city. The right of way may be transferred to the city without cost to remain in use for public road purposes and will automatically revert to the state if it ceases to be used for public road purposes or if the unrestricted motor vehicle lanes are reduced in number or width.*

12. Municipal Utility Relocation Reimbursement

Brazoria County - Consider the approval of a request from the City of West Columbia to make the relocation of the City of West Columbia's utility facilities required by the SH 36 highway improvement project an expense of the state under Transportation Code §203.092(a-4) (MO) *During the 86th Legislative Session, the Texas legislature enacted SB 1512, which amended Texas Transportation Code, Section 203.092, to establish provisions for the relocation of a utility facility required by improvement of the state highway system at the expense of the state. In accordance with SB 1512, the department has determined that:*

(1) the utility's financial condition prevents it from being able to pay the cost in full or in part or, if paid at that time, the payment would adversely affect the utility's ability to operate or provide essential services to its customers;

(2) the utility is owned by a political subdivision, City of West Columbia, that has a population under 5,000; and

(3) the utility is located in Brazoria County, a county that has had at least five federal disaster declaration in the past five years.

43 TAC §21.25 sets forth the requirements for a utility to qualify for reimbursement under this program. Payment for this relocation will not cause the department to exceed \$10 million in any fiscal year

13. Eminent Domain Proceedings

Various Counties - Consider the authorization of the filing of condemnation proceedings to acquire real property by eminent domain for non-controlled and controlled access highways (see attached itemized list) (MO)

Commission findings, determinations, and authorizations for the state, by motion made in accordance with Senate Bill 18, 82nd Legislature, to acquire by eminent domain, upon the payment of adequate and just compensation, various ownership interests in specific parcels of real property that are needed to develop or improve both non-controlled and controlled access state highways, to include requesting the state attorney general to bring and pursue condemnation suits relating to those specific parcels of real property described in the attached itemized list.

14. **Routine Minute Orders and Reports**

a. **Donations to the Department**

Various Districts - Consider the acknowledgment of donations with a value of \$500 or more, including donations of money, materials, services, or real property, that are made to the department for the purpose of assisting the department in carrying out its functions and duties or for improving access to or from a highway on the state highway system (see attached itemized list) (MO)

State statutes require the commission to acknowledge the acceptance of a gift to the department that is valued at \$500 or more. By the adoption of this minute order, the commission acknowledges the receipt and acceptance of the property specified in the minute order. minute order.

14. Routine Minute Orders and Reports (continued)

b. Real Estate Dispositions

The commission must approve the sales, transfers, and exchanges of state rights of way and other real properties that are no longer needed for a state highway purpose. It must also approve, accept, and acknowledge donations to the state of real property that is valued at \$500 or more.

- Hidalgo County I-2 Consider the sale of right of way to an abutting landowner (MO)
 The district has determined that the land is no longer needed for highway purposes. An
- abutting landowner has requested to purchase the land, and it may be sold to the
 Williamson County US 183 Consider the sale of right of way to an abutting landowner (MO)
 The district has determined that the land is no longer needed for highway purposes. An abutting landowner has requested to purchase the land, and it may be sold to the requester.

c. Reports

(1) Compliance Division Report

State law requires the commission to establish a compliance program, which must include a Compliance Division to oversee the program. The Compliance Division is responsible for acting to prevent and detect serious breaches of department policy, fraud, waste, and abuse of office, including any acts of criminal conduct within the department. The Compliance Division is required to provide a monthly report to the commission regarding investigations and a summary of information relating to trends and recommendations.

(2) Central Texas Turnpike System

Travis and Williamson Counties - FY 2022 Central Texas Turnpike System Annual Inspection (Report)

(The commission financed a portion of the costs of the Central Texas Turnpike System System) with obligations issued pursuant to a trust indenture dated July 15, 2002. In accordance with Section 707 of the trust indenture, the commission has caused the general engineering consultant to make an inspection of the System and submit a report to the commission on or before the 90th day prior to the end of the fiscal year.

(3) Quarterly Investment Report for all of the funds invested at the direction of the commission (Report)

This is a presentation of the quarterly investment report for the investment of: (1) funds held by the Bank of New York Mellon, as trustee, under the Indenture of Trust securing the Central Texas Turnpike System toll revenue obligations; (2) funds for the pre-paid TxTag account held by the Bank of New York Mellon, acting as custodian; (3) funds held by Amegy Bank, a Division of ZB, National Association, as trustee, under the Trust Agreement securing the I-35E Managed Lanes Project toll revenue obligations; and (4) funds held by U.S. Bank National Association, as trustee, under the Master Trust Agreement securing the SH 249 System toll revenue obligations.

 (4) State Highway 249 System
 Grimes and Montgomery Counties - Quarterly Traffic and Operating Report for the State Highway 249 System (Report)

The commission financed a portion of the costs of the system with obligations issued pursuant to a trust agreement. In accordance with Section 709 of the trust agreement, the commission is providing to the trustee, general engineering consultant, and traffic consultant a report of general information regarding the system for the preceding fiscal quarter. A copy of the report is being filed with the Municipal Securities Rulemaking Board through its Electronic Municipal Markets Access System.

14. Routine Minute Orders and Reports (continued)

sections of highways in the state.

- d. Land Acquisitions for Facilities
 Angelina County Consider the grant of authority to the department to acquire real property for facilities (MO)
 The department is in the process of acquiring real property for the construction of new facilities and the expansion of existing facility sites. Funds for the purchase of these properties were appropriated by the 87th Legislature, Supplemental Appropriations Act for the 2022-23 Biennium. The department requests the commission's authorization to enter into purchase contracts and related documents to complete the acquisition of the listed properties.
 e. Speed Zones
 Various Counties Consider the establishment or alteration of regulatory and construction speed zones on various sections of highways in the state (MO)
 This minute order establishes or alters regulatory and construction speed zones on various
- 15. **Executive Session** Pursuant to Government Code, Chapter 551 **Section 551.071** - Consultation with and advice from legal counsel regarding any item on this agenda, pending or contemplated litigation, or other legal matters.

OPEN COMMENT PERIOD - At the conclusion of all other agenda items, the commission will allow an open comment period, not to exceed one hour, to receive public comment on any other matter that is under the jurisdiction of the department. No action will be taken. Each speaker will be allowed a maximum of three minutes. Speakers must be signed up prior to the beginning of the open comment period.

ADJOURN

* * *

NOTE:

Enumerated agenda items are assigned numbers for ease of reference and will not necessarily be considered by the commission in that order. Agenda items with (MO) are those for which the commission is considering an action.

TEXAS TRANSPORTATION COMMISSION AGENDA Attached Lists May 26, 2022

Highway Improvement and Other Transportation Facilities						
<u>State Let (a)</u>						
D' (<u>County</u>	<u>Highway</u>	<u>Controlling</u>			
<u>Dist.</u>	<u>Name</u>	<u>Number</u>	Project No.			
AMA	ARMSTRONG	US 287	C 42-3-44			
AMA	CARSON	US 60	STP 2022(502)HES			
ATL	HARRISON	FM 3001	BR 2022(504)			
ATL	HARRISON	CS	STP 2021(657)FRS1			
AUS	TRAVIS	SH 130	F 2022(500)			
AUS	TRAVIS	IH 35	F 2022(340)			
AUS	TRAVIS	IH 35	F 2022(499)			
BMT	CHAMBERS	SH 146	C 389-2-57			
BMT	JASPER	VA	STP 2021(242)SRS			
		IH 10	C 28-14-120			
BMT	ORANGE					
BMT	TYLER	US 287	STP 2022(536)			
BRY	BURLESON	SH 21	F 2022(488)			
BRY	BURLESON	CR	BR 1702(439)			
BWD	BROWN	US 377	F 2022(487)			
BWD	BROWN	VA	STP 2022(592)HES			
BWD	EASTLAND	SH 112	F 2022(486)			
BWD	EASTLAND	VA	F 2022(553)			
CHS	FOARD	FM 1594	STP 2022(362)HES			
CRP	ARANSAS	BS 35-L	C 180-5-65			
CRP	KARNES	US 181	STP 2022(543)HES			
CRP	NUECES	SH 358	F 2022(547)			
DAL	COLLIN	FM 544	CM 2022(513)			
DAL	DALLAS	US 175	CM 2022(485)			
DAL	DENTON	CS	BR 2019(601)			
DAL	KAUFMAN	US 80	F 2022(483)			
DAL	NAVARRO	IH 45	C 92-6-105			
DILL		111 15	0 92 0 105			
ELP	EL PASO	SL 375	NH 2019(168)			
FTW	ERATH	US 377	BR 2022(473)			
	TARRANT	VA	C 902-00-314			
FTW						
FTW	TARRANT	IH 820	F 2022(672)			
HOU	BRAZORIA	FM 1495	С 587-1-64			
HOU	MONTGOMERY	SL 494	BR 2022(511)			
-			(

Highway Improvement and Other Transportation Facilities

<u>Highway Improvement and Other Transportation Facilities</u> State Let (a)						
<u>Dist.</u> LBB	<u>County</u> <u>Name</u> LAMB	<u>Highway</u> <u>Number</u> US 84	<u>Controlling</u> <u>Project No.</u> STP 2022(493)HES			
LFK	NACOGDOCHES	FM 1878	F 2022(494)			
LFK	POLK	US 59	NH 2013(222)			
LFK	POLK	CR	BR 2B20(098)			
LFK	SHELBY	CR	BR 2B20(125)			
LRD	LA SALLE	CR	BR 2021(502)			
LRD	WEBB	IH 35	F 2022(669)			
ODA	ECTOR	SH 302	STP 2022(497)HES			
ODA	LOVING	SH 302	F 2022(496)			
ODA	MIDLAND	IH 20	F 2022(356)			
PAR	GRAYSON	BU 377B	F 2022(530)			
PAR	HOPKINS	CR	BR 2021(759)			
PHR	CAMERON	CS	STP 2020(601)TAPS			
PHR	HIDALGO	VA	STP 2022(728)HES			
SAT	BEXAR	VA	C 915-00-238			
SAT	BEXAR	VA	C 915-00-237			
SAT	BEXAR	SH 16	CM 2022(476)			
SAT	KERR	SH 16	STP 2022(403)HES			
SJT	TOM GREEN	BU 67-H	STP 2022(508)HES			
TYL	ANDERSON	VA	STP 2022(533)HES			
TYL	GREGG	SS 502	STP 2022(532)HES			
TYL	GREGG	SH 135	F 2022(024)			
TYL	GREGG	CS	STP 2022(534)HESG			
WAC	BELL	SH 36	STP 2022(479)HES			
WAC	HILL	SH 81	F 2022(477)			
WAC	HILL	SH 174	BR 2022(480)			
WAC	LIMESTONE	FM 39	F 2022(481)			
WAC	MCLENNAN	US 84	STP 2022(478)HES			
WFS	WICHITA	VA	F 2022(378)			
WFS	WICHITA	VA	F 2022(377)			
YKM	AUSTIN	CR	BR 2020(686)			
YKM	DEWITT	FM 108	F 2022(491)			
YKM	GONZALES	FM 2067	BR 2022(492)			
YKM	MATAGORDA	SH 35	F 2022(490)			

Routine Maintenance State Let (b)

<u>State Let (b)</u>			
	<u>County</u>	<u>Highway</u>	<u>Controlling</u>
<u>Dist.</u>	<u>Name</u>	<u>Number</u>	<u>Project No.</u>
ABL	HOWARD	IH 20	RMC - 639195001
ABL	SCURRY	US 84	RMC - 639198001
ABL	TAYLOR	IH 20	RMC - 639197001
AMA	POTTER	IH 40	RMC - 640100001
AMA	RANDALL	IH 27	MMC - 639763001
BRY	BRAZOS	SH 6	RMC - 640070001
BRY	WALKER	IH 45	RMC - 640051001
	DDOWNI	110 277	DMC (20595001
BWD	BROWN	US 377	RMC - 639585001
CRP	JIM WELLS	US 281	RMC - 640088001
CRP	NUECES	SH 361	RMC - 639689001
ena	Nelels	511 501	10000 059009001
DAL	COLLIN	US 380	RMC - 639073001
DAL	DALLAS	SL 12	RMC - 639679001
DAL	KAUFMAN	US 80	RMC - 639674001
DAL	KAUFMAN	IH 20	RMC - 639639001
DAL	KAUFMAN	IH 20	RMC - 639638001
DAL	NAVARRO	IH 45	RMC - 639671001
DAL	NAVARRO	IH 45	RMC - 639708001
DAL	NAVARRO	FM 1129	RMC - 639431001
ELP	CULBERSON	IH 10	RMC - 639851001
ELP	EL PASO	IH 10	RMC - 639982001
FTW	JOHNSON	IH 35W	RMC - 639825001
FTW	JOHNSON	FM 917	RMC - 639829001 RMC - 639829001
FTW	PARKER	IH 20	RMC - 638310001
FTW	PARKER	IH 20 IH 20	RMC - 639536001
FTW	TARRANT	IH 20 IH 30	RMC - 640003001
FTW	WISE	US 81	RMC - 638308001
FTW	WISE	US 380	MMC - 639890001
1 1 **	WISL	05 500	WINC - 057070001
HOU	HARRIS	SL 8	RMC - 639650001
HOU	HARRIS	IH 10	RMC - 639217001
HOU	HARRIS	SH 99	RMC - 639155001
HOU	HARRIS	IH 10	RMC - 639869001
HOU	MONTGOMERY	IH 45	RMC - 638849001
HOU	WALLER	US 290	RMC - 638942001
HOU	WALLER	US 290	RMC - 639668001
LBB	GARZA	US 84	MMC - 639998001
LBB	LUBBOCK	US 87	RMC - 639187001

Routine Maintenance

Eminent Domain

State Let (b)			
	County	<u>Highway</u>	<u>Controlling</u>
<u>Dist.</u>	Name	Number	Project No.
PAR	HOPKINS	IH 30	MMC - 639922001
PAR	HOPKINS	SH 19	RMC - 639898001
PAR	LAMAR	US 82	MMC - 640041001
		111.25	DMG (20772001
SAT	BEXAR	IH 35	RMC - 638772001
SAT	GUADALUPE	IH 10	MMC - 640000001
SAT	GUADALUPE	UA 90	RMC - 637441001
SJT	TOM GREEN	SH 208	RMC - 640098001
TYL	HENDERSON	SH 31	MMC - 639999001
WAC	FALLS	US 77	RMC - 639957001
WAC	HILL	FM 308	RMC - 639956001
WAC	LIMESTONE	SH 7	RMC - 639958001
WAC	MCLENNAN	SH 6	RMC - 639955001
ҮКМ	GONZALES	US 183	RMC - 637968001
1 1/1/1	UUNZALLS	05 105	KIVIC - 03/300001

Non-Controlled Access County Exhibit **ROW CSJ No.** <u>Highway</u> Parcel Brazoria SH 36 2 0188-04-041 1 70 Brazoria FM 518 3416-01-014 110 9 Denton FM 1173 1059-02-003 P00055948 8 P00055949 Denton FM 1173 1059-02-003 7 Denton FM 1173 1059-02-003 P00055951 FM 1173 6 1059-02-003 P00055952 Denton 5 P00055953,P00055953.002 Denton FM 1173 1059-02-003 1059-02-003 Denton FM 1173 19 P00055954 72 221 Fort Bend FM 723 0188-09-047 29 FM 2275 3 Gregg 2158-01-025 Harris FM 2100 71 1062-02-021 216 Hidalgo FM 676 21 1064-01-047 41E Hidalgo FM 676 22 1064-01-047 42E 27 379 Lubbock FM 1585 1502-01-037 43 0338-07-022 723 Montgomery SH 105 Montgomery SH 105 41 0338-07-022 724A Montgomery SH 105 42 0338-07-022 724B Starr SL 195 10 3632-01-004 112 20 Starr SL 195 3632-01-004 113 Starr SL 195 54 114 3632-01-004 Starr SL 195 55 3632-01-004 116 SL 195 23 3632-01-004 120 Starr Starr SL 195 56 3632-01-004 123

Italicized text in document is provided for informational purposes only and is not part of the official posted agenda.

131

3632-01-004

57

SL 195

Starr

<u>Eminent Domain</u> Non-Controlled Access (continued)					
		F	DOW COLN.	Davaal	
<u>County</u> Starr	<u>Highway</u> SL 195	<u>Exhibit</u> 58	<u>ROW CSJ No.</u> 3632-01-004	<u>Parcel</u> 137	
Starr	SL 195 SL 195	60	3632-01-004	140	
Starr	SL 195 SL 195	59	3632-01-004	140	
Starr	SL 195 SL 195	1	3632-01-004	64	
Starr	SL 195 SL 195	4	3632-01-005	75	
Starr	SL 195	11	3632-01-005	88	
Starr	SL 195	12	3632-01-006	91	
Starr	SL 195	12	3632-01-006	92	
Starr	SL 195	13	3632-01-006	93	
Starr	SL 195	15	3632-01-006	94	
Starr	SL 195	16	3632-01-006	96	
Starr	SL 195	17	3632-01-006	104	
Starr	SL 195	18	3632-01-006	105	
Travis	RM 620	49	0683-02-081	25	
Travis	RM 620	24	0683-02-083	101	
Victoria	US 77	25	2350-01-068	P00059745	
Victoria	US 77	26	2350-01-068	P00059746	
Victoria	US 77	30	2350-01-068	P00059747,P00059747.002	
Victoria	US 77	28	2350-01-068	P00059748	
Victoria	US 77	29	2350-01-068	P00059749	
Victoria	US 77	40	2350-01-068	P00059753	
Victoria	US 77	44	2350-01-068	P00059754	
Victoria	US 77	45	2350-01-068	P00059755	
Victoria	US 77	31	2350-01-068	P00059756	
Victoria	US 77	32	2350-01-068	P00059757	
Victoria	US 77	33	2350-01-068	P00059758	
Victoria	US 77	46	2350-01-068	P00059759	
Victoria	US 77	34	2350-01-068	P00059762	
Victoria	US 77	47	2350-01-068	P00059763	
Wharton	US 59	52	0089-07-163	2	
Wharton	US 59	35	0089-07-163	4	
Wharton	US 59	69	0089-07-163	5	
Wharton	US 59	65	0089-08-104	6	
Wharton	US 59	53	0089-08-104	7	
Wharton	US 59	36	0089-08-104	9	
Wharton	US 59	37	0089-08-104	12	
Wharton	US 59	64	0089-08-104	15	
Wharton	US 59	38	0089-08-104	16	
Wharton	US 59	50	0089-08-104	17	
Wharton	US 59	51	0089-08-104	18	
Wharton	US 59	63	0089-08-104	19	
Wharton	US 59	39	0089-08-104	20	
Wharton	US 59	48	0089-08-104	22	
Wharton	US 59	66	0089-08-104	23	
Wharton	US 59	68	0089-08-104	24	
Wharton	US 59	61	0089-08-104	26	
Wharton	US 59	67	0089-08-104	27	
Wharton	US 59	62	0089-08-104	28	

Eminent Domain Controlled Access

County Highway Exhibit ROW CSJ No. Parcel Colorado HI 10 DD 0271-01-081 29 Colorado HI 10 C 0271-01-081 47 Colorado HI 10 G 0271-01-081 73 Colorado HI 10 H 0271-01-082 73 Comal HI 35 ZZ 0016-04-114 37 Comal HI 35 AAA 0016-04-114 37 Comal HI 45 R 0675-01-076 P00058796 Freestone HI 45 K 0675-01-076 P00058803 Freestone HI 45 D 0675-01-076 P00058804 Freestone HI 45 J 0675-01-076 P00058805 Freestone HI 45 M 0675-01-076 P00058805 Freestone HI 45 L 0675-01-076 P00069413 Jefferson HI 10 F 0028-13-138 19 Travis HI 35 NNN <t< th=""><th>Controlled Acces</th><th><u>s</u></th><th></th><th></th><th></th></t<>	Controlled Acces	<u>s</u>			
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	<u>County</u>	<u>Highway</u>	<u>Exhibit</u>	ROW CSJ No.	Parcel
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	Colorado	IH 10	DD	0271-01-081	29
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	Colorado	IH 10	Р	0271-01-081	47
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	Colorado	IH 10	CC	0271-01-081	56
$\begin{array}{c cccc} Comal & IH 35 & ZZ & 0016-04-114 & 37 \\ Comal & IH 35 & AAA & 0016-04-114 & 38 \\ Freestone & IH 45 & R & 0675-01-076 & P00058796 \\ Freestone & IH 45 & Q & 0675-01-076 & P00058803 \\ Freestone & IH 45 & B & 0675-01-076 & P00058804 \\ Freestone & IH 45 & D & 0675-01-076 & P00058804 \\ Freestone & IH 45 & D & 0675-01-076 & P00058805 \\ Freestone & IH 45 & J & 0675-01-076 & P00058807 \\ Freestone & IH 45 & J & 0675-01-076 & P00058807 \\ Freestone & IH 45 & J & 0675-01-076 & P00058807 \\ Freestone & IH 45 & L & 0675-02-093 & P00060409 \\ Freestone & IH 45 & L & 0675-02-093 & P00060413 \\ Jefferson & IH 10 & F & 0028-13-138 & 19 \\ Tararant & IH 820 & W & 0008-13-242 & 508A \\ Travis & IH 35 & E & 0015-10-065 & P00000934 \\ Travis & IH 35 & S & 0015-13-406 & P00001047 \\ Travis & IH 35 & S & 0015-13-406 & P00001047 \\ Travis & IH 35 & J & 0015-13-406 & P00001047 \\ Travis & IH 35 & J & 0015-13-406 & P00001047 \\ Travis & IH 35 & T & 0015-13-406 & P00001070 \\ Travis & IH 35 & T & 0015-13-406 & P00001070 \\ Travis & IH 35 & T & 0015-13-406 & P00001074 \\ Travis & IH 35 & T & 0015-13-406 & P00001074 \\ Travis & IH 35 & T & 0015-13-406 & P00001070 \\ Travis & IH 35 & V & 0015-13-406 & P00001071 \\ Travis & IH 35 & V & 0015-13-406 & P00001074 \\ Travis & IH 35 & T & 0015-13-406 & P00001105 \\ Travis & IH 35 & V & 0015-13-406 & P00001105 \\ Travis & IH 35 & V & 0015-13-406 & P00001105 \\ Travis & IH 35 & V & 0015-13-406 & P00001105 \\ Travis & IH 35 & V & 0015-13-406 & P00001105 \\ Travis & IH 35 & V & 0015-13-406 & P00001105 \\ Travis & IH 35 & V & 0015-13-406 & P00001105 \\ Travis & IH 35 & V & 0015-13-406 & P00001105 \\ Travis & IH 35 & V & 0015-13-406 & P00001105 \\ Travis & IH 35 & V & 0015-13-406 & P00001105 \\ Travis & IH 35 & V & 0015-13-406 & P00001120 \\ Travis & IH 35 & S & 0015-13-406 & P00056297 \\ Travis & IH 35 & V & 0015-13-406 & P00056297 \\ Travis & IH 35 & FF & 0016-01-122 & P00001323 \\ Travis & IH 35 & FF & 0016-01-122 & P00001323 \\ Travis & IH 35 & II & 0016-01-122 & P00001345 \\ Travis & IH 35 & IL & 0016-01-122 & P00001345 $	Colorado	IH 10	G	0271-01-081	79
$\begin{array}{c c c c c c c c c c c c c c c c c c c $	Colorado	IH 10	Н	0271-01-082	73
$\begin{array}{c c c c c c c c c c c c c c c c c c c $	Comal	IH 35	ZZ	0016-04-114	37
FreestoneIH 45R $0675-01-076$ P00058796FreestoneIH 45Q $0675-01-076$ P00058801FreestoneIH 45B $0675-01-076$ P00058801FreestoneIH 45D $0675-01-076$ P00058803FreestoneIH 45D $0675-01-076$ P00058805FreestoneIH 45J $0675-01-076$ P00058807FreestoneIH 45J $0675-01-076$ P00058807FreestoneIH 45L $0675-02-093$ P00060419FreestoneIH 45L $0675-02-093$ P00060413JeffersonIH 10F $0028+13-138$ 19TarantIH 820W $0008+13-242$ $508A$ TravisIH 35E $0015-10-065$ P00000945TravisIH 35NNN $0015-13-406$ P00001047TravisIH 35S $0015-13-406$ P00001048TravisIH 35U $0015-13-406$ P00001070TravisIH 35N $0015-13-406$ P00001070TravisIH 35T $0015-13-406$ P00001070TravisIH 35N $0015-13-406$ P00001070TravisIH 35N $0015-13-406$ P00001070TravisIH 35N $0015-13-406$ P00001070TravisIH 35V $0015-13-406$ P00001107TravisIH 35N $0015-13-406$ P00001107TravisIH 35N $0015-13-406$ P00001107	Comal	IH 35	AAA	0016-04-114	38
FreestoneIH 45Q $0675 \cdot 01 \cdot 076$ P00058799FreestoneIH 45K $0675 \cdot 01 \cdot 076$ P00058801FreestoneIH 45B $0675 \cdot 01 \cdot 076$ P00058803FreestoneIH 45D $0675 \cdot 01 \cdot 076$ P00058807FreestoneIH 45J $0675 \cdot 01 \cdot 076$ P00058807FreestoneIH 45J $0675 \cdot 01 \cdot 076$ P00058807FreestoneIH 45L $0675 \cdot 02 \cdot 093$ P00060409FreestoneIH 45L $0675 \cdot 02 \cdot 093$ P00060413JeffersonIH 10F $0028 \cdot 13 \cdot 138$ 19TarantIH 820W $0008 \cdot 13 \cdot 242$ $508A$ TravisIH 35E $0015 \cdot 10 \cdot 065$ P00000945TravisIH 35NNN $0015 \cdot 13 \cdot 406$ P00001047TravisIH 35U $0015 \cdot 13 \cdot 406$ P00001048TravisIH 35U $0015 \cdot 13 \cdot 406$ P00001070TravisIH 35N $0015 \cdot 13 \cdot 406$ P00001070TravisIH 35T $0015 \cdot 13 \cdot 406$ P00001074TravisIH 35N $0015 \cdot 13 \cdot 406$ P00001170TravisIH 35N $0015 \cdot 13 \cdot 406$ P000011105 </td <td></td> <td>IH 45</td> <td>R</td> <td>0675-01-076</td> <td>P00058796</td>		IH 45	R	0675-01-076	P00058796
FreestoneIH 45K $0675-01-076$ P00058801FreestoneIH 45B $0675-01-076$ P00058803FreestoneIH 45D $0675-01-076$ P00058807FreestoneIH 45J $0675-01-076$ P00058807FreestoneIH 45J $0675-01-076$ P00058807FreestoneIH 45L $0675-02-093$ P00060409FreestoneIH 45L $0675-02-093$ P00060413JeffersonIH 10F $0028+13-138$ 19TarantIH 820W $0008+13-242$ $508A$ TravisIH 35E $0015-10-065$ P00000934TravisIH 35X $0015-13-406$ P00001047TravisIH 35S $0015-13-406$ P00001048TravisIH 35U $0015-13-406$ P00001070TravisIH 35UU $0015-13-406$ P00001070TravisIH 35T $0015-13-406$ P00001070TravisIH 35T $0015-13-406$ P00001105TravisIH 35T $0015-13-406$ P00001107TravisIH 35V $0015-13-406$ P00001107TravisIH 35V $0015-13-406$ P00001107TravisIH 35V $0015-13-406$ P00001110TravisIH 35V $0015-13-406$ P00001110TravisIH 35S $0015-13-406$ P00001107TravisIH 35S $0015-13-406$ P00001110 </td <td></td> <td></td> <td></td> <td></td> <td></td>					
FreestoneIH 45B $0675-01-076$ P00058803FreestoneIH 45C $0675-01-076$ P00058805FreestoneIH 45J $0675-01-076$ P00058805FreestoneIH 45J $0675-01-076$ P00058807FreestoneIH 45L $0675-02-093$ P00060409FreestoneIH 45L $0675-02-093$ P00060413JeffersonIH 10F $0028+13-138$ 19TarrantIH 820W $0008+13-242$ $508A$ TravisIH 35E $0015-10-065$ P00000934TravisIH 35NNN $0015-13-406$ P00001047TravisIH 35S $0015-13-406$ P00001047TravisIH 35U $0015-13-406$ P00001060TravisIH 35UU $0015-13-406$ P00001070TravisIH 35T $0015-13-406$ P00001070TravisIH 35T $0015-13-406$ P00001070TravisIH 35T $0015-13-406$ P00001106TravisIH 35N $0015-13-406$ P000011070TravisIH 35V $0015-13-406$ P00001110TravisIH 35V $0015-13-406$ P00001110TravisIH 35V $0015-13-406$ P00001110TravisIH 35V $0015-13-406$ P00001110TravisIH 35N $0015-13-406$ P00001110TravisIH 35N $0015-13-406$ P00001110<					
FreestoneIH 45C $0675-01-076$ P00058804FreestoneIH 45J $0675-01-076$ P00058805FreestoneIH 45J $0675-02-093$ P00060409FreestoneIH 45L $0675-02-093$ P00060413JeffersonIH 10F $0028+13-138$ 19TarantIH 820W $0008-13-242$ $508A$ TravisIH 35E $0015-10-065$ P00000934TravisIH 35NNN $0015-10-065$ P00000945TravisIH 35X $0015-13-406$ P00001047TravisIH 35S $0015-13-406$ P00001048TravisIH 35U $0015-13-406$ P00001050TravisIH 35U $0015-13-406$ P00001066TravisIH 35UU $0015-13-406$ P00001070TravisIH 35N $0015-13-406$ P00001074TravisIH 35T $0015-13-406$ P00001074TravisIH 35N $0015-13-406$ P00001105TravisIH 35V $0015-13-406$ P00001107TravisIH 35V $0015-13-406$ P00001110TravisIH 35N $0015-13-406$ P00001116TravisIH 35V $0015-13-406$ P00001110TravisIH 35N $0015-13-406$ P00001110TravisIH 35S $0015-13-406$ P00001120TravisIH 35S $0015-13-406$ P00056298					
FreestoneIH 45D $0675-01-076$ P00058805FreestoneIH 45J $0675-02-093$ P00060409FreestoneIH 45L $0675-02-093$ P00060413JeffersonIH 10F $0028+13-138$ 19TarantIH 820W $0008-13-242$ $508A$ TravisIH 35E $0015-10-065$ P00000943TravisIH 35NNN $0015-10-065$ P00000944TravisIH 35S $0015-13-406$ P00001047TravisIH 35S $0015-13-406$ P00001048TravisIH 35O $0015-13-406$ P00001066TravisIH 35U $0015-13-406$ P00001066TravisIH 35U $0015-13-406$ P00001076TravisIH 35U $0015-13-406$ P00001076TravisIH 35T $0015-13-406$ P00001076TravisIH 35N $0015-13-406$ P00001074TravisIH 35T $0015-13-406$ P00001105TravisIH 35I $0015-13-406$ P00001116TravisIH 35V $0015-13-406$ P00001116TravisIH 35V $0015-13-406$ P00001116TravisIH 35V $0015-13-406$ P00056296TravisIH 35V $0015-13-406$ P00056296TravisIH 35S $0016-01-122$ P00001329TravisIH 35S $0016-01-122$ P00001329					
$\begin{array}{c c c c c c c c c c c c c c c c c c c $					
FreestoneIH 45M $0675-02-093$ P00060409FreestoneIH 45L $0675-02-093$ P00060413JeffersonIH 10F $0028+13-138$ 19TarrantIH 820W $0008+13-242$ $508A$ TravisIH 35E $0015-10-065$ P00000934TravisIH 35NNN $0015-10-065$ P00000945TravisIH 35X $0015-13-406$ P00001047TravisIH 35S $0015-13-406$ P00001047TravisIH 35U $0015-13-406$ P00001050TravisIH 35O $0015-13-406$ P00001066TravisIH 35UU $0015-13-406$ P00001070TravisIH 35T $0015-13-406$ P00001070TravisIH 35T $0015-13-406$ P00001074TravisIH 35T $0015-13-406$ P00001010TravisIH 35Y $0015-13-406$ P00001110TravisIH 35I $0015-13-406$ P00001110TravisIH 35V $0015-13-406$ P00001116TravisIH 35V $0015-13-406$ P000056278TravisIH 35V $0015-13-406$ P00056278TravisIH 35S $0015-13-406$ P00056296TravisIH 35S $0015-13-406$ P00056296TravisIH 35S $0015-13-406$ P00056296TravisIH 35S $0016-01-122$ P00001323					
$\begin{array}{c c c c c c c c c c c c c c c c c c c $					
JeffersonIH 10F $0028-13-138$ 19TarrantIH 820W $0008-13-242$ $508A$ TravisIH 35E $0015-10-065$ $P00000934$ TravisIH 35NNN $0015-10-065$ $P00000945$ TravisIH 35X $0015-13-406$ $P00001047$ TravisIH 35S $0015-13-406$ $P00001047$ TravisIH 35U $0015-13-406$ $P00001047$ TravisIH 35O $0015-13-406$ $P00001050$ TravisIH 35U $0015-13-406$ $P00001070$ TravisIH 35T $0015-13-406$ $P00001074$ TravisIH 35T $0015-13-406$ $P00001074$ TravisIH 35N $0015-13-406$ $P00001105$ TravisIH 35TT $0015-13-406$ $P00001105$ TravisIH 35I $0015-13-406$ $P00001110$ TravisIH 35RR $0015-13-406$ $P00001110$ TravisIH 35V $0015-13-406$ $P00001120$ TravisIH 35VV $0015-13-406$ $P000056278$ TravisIH 35S $0015-13-406$ $P00056278$ TravisIH 35BB $0016-01-122$ $P00001323$ TravisIH 35S $0015-01-122$ $P00001323$ TravisIH 35FF $0016-01-122$ $P00001324$ TravisIH 35G $0016-01-122$ $P00001345$ TravisIH 35II $0016-01-1$					
TarrantIH 820W0008-13-242508ATravisIH 35E0015-10-065P00000934TravisIH 35NNN0015-10-065P00000945TravisIH 35X0015-13-406P00001047TravisIH 35S0015-13-406P00001048TravisIH 35U0015-13-406P00001050TravisIH 35O0015-13-406P00001050TravisIH 35UU0015-13-406P00001070TravisIH 35T0015-13-406P00001074TravisIH 35T0015-13-406P00001094TravisIH 35N0015-13-406P00001105TravisIH 35T0015-13-406P00001105TravisIH 35I0015-13-406P00001110TravisIH 35R0015-13-406P00001116TravisIH 35R0015-13-406P00001116TravisIH 35V0015-13-406P00056278TravisIH 35V0015-13-406P00056296TravisIH 35S0015-13-406P00056296TravisIH 35S0015-13-406P00056297TravisIH 35S0015-13-406P00056297TravisIH 35S0015-13-406P00056307TravisIH 35S0015-13-406P00056307TravisIH 35FF0016-01-122P00001313TravisIH 35PP0016-01-12					
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$					
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$					
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$					
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$					
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$					
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$					
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$					
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$					
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$					
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$					
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$					
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$					
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$					
TravisIH 35VV0015-13-406P00001120TravisIH 35WW0015-13-406P00056278TravisIH 35V0015-13-406P00056291TravisIH 35XX0015-13-406P00056296TravisIH 35AA0015-13-406P00056303TravisIH 35SS0015-13-406P00056307TravisIH 35SS0016-01-122P00001313TravisIH 35BB0016-01-122P00001323TravisIH 35FF0016-01-122P00001329TravisIH 35OO0016-01-122P00001342TravisIH 35GG0016-01-122P00001342TravisIH 35II0016-01-122P00001345TravisIH 35LL0016-01-122P00001348TravisIH 35LL0016-01-122P00001348					
TravisIH 35WW0015-13-406P00056278TravisIH 35V0015-13-406P00056291TravisIH 35XX0015-13-406P00056296TravisIH 35AA0015-13-406P00056303TravisIH 35SS0015-13-406P00056307TravisIH 35BB0016-01-122P00001313TravisIH 35FF0016-01-122P00001323TravisIH 35FF0016-01-122P00001329TravisIH 35PP0016-01-122P00001342TravisIH 35GG0016-01-122P00001342TravisIH 35II0016-01-122P00001345TravisIH 35LL0016-01-122P00001348TravisIH 35LL0016-01-122P00001349					
TravisIH 35V0015-13-406P00056291TravisIH 35XX0015-13-406P00056296TravisIH 35AA0015-13-406P00056303TravisIH 35SS0015-13-406P00056307TravisIH 35BB0016-01-122P00001313TravisIH 35YY0016-01-122P00001323TravisIH 35FF0016-01-122P00001329TravisIH 35OO0016-01-122P00001329TravisIH 35PP0016-01-122P00001342TravisIH 35II0016-01-122P00001342TravisIH 35II0016-01-122P00001345TravisIH 35II0016-01-122P00001345TravisIH 35II0016-01-122P00001346TravisIH 35IL0016-01-122P00001348TravisIH 35LL0016-01-122P00001348					
TravisIH 35XX0015-13-406P00056296TravisIH 35AA0015-13-406P00056303TravisIH 35SS0015-13-406P00056307TravisIH 35BB0016-01-122P00001313TravisIH 35YY0016-01-122P00001323TravisIH 35FF0016-01-122P00001329TravisIH 35OO0016-01-122P00001329TravisIH 35PP0016-01-122P00001342TravisIH 35GG0016-01-122P00001342TravisIH 35II0016-01-122P00001345TravisIH 35LL0016-01-122P00001348TravisIH 35LL0016-01-122P00001348					
TravisIH 35AA0015-13-406P00056303TravisIH 35SS0015-13-406P00056307TravisIH 35BB0016-01-122P00001313TravisIH 35YY0016-01-122P00001323TravisIH 35FF0016-01-122P00001329TravisIH 35OO0016-01-122P00001328TravisIH 35PP0016-01-122P00001342TravisIH 35GG0016-01-122P00001342TravisIH 35II0016-01-122P00001345TravisIH 35LL0016-01-122P00001348TravisIH 35LL0016-01-122P00001349					
TravisIH 35SS0015-13-406P00056307TravisIH 35BB0016-01-122P00001313TravisIH 35YY0016-01-122P00001323TravisIH 35FF0016-01-122P00001329TravisIH 35OO0016-01-122P00001338TravisIH 35PP0016-01-122P00001342TravisIH 35GG0016-01-122P00001345TravisIH 35II0016-01-122P00001345TravisIH 35II0016-01-122P00001346TravisIH 35IL0016-01-122P00001348TravisIH 35LL0016-01-122P00001349					
TravisIH 35BB0016-01-122P00001313TravisIH 35YY0016-01-122P00001323TravisIH 35FF0016-01-122P00001329TravisIH 35OO0016-01-122P00001338TravisIH 35PP0016-01-122P00001342TravisIH 35GG0016-01-122P00001345TravisIH 35II0016-01-122P00001346TravisIH 35IL0016-01-122P00001348TravisIH 35LL0016-01-122P00001349					
TravisIH 35YY0016-01-122P00001323TravisIH 35FF0016-01-122P00001329TravisIH 35OO0016-01-122P00001338TravisIH 35PP0016-01-122P00001342TravisIH 35GG0016-01-122P00001345TravisIH 35II0016-01-122P00001346TravisIH 35II0016-01-122P00001348TravisIH 35LL0016-01-122P00001349					
TravisIH 35FF0016-01-122P00001329TravisIH 35OO0016-01-122P00001338TravisIH 35PP0016-01-122P00001342TravisIH 35GG0016-01-122P00001345TravisIH 35II0016-01-122P00001346TravisIH 35IL0016-01-122P00001348TravisIH 35LL0016-01-122P00001349					
TravisIH 35OO0016-01-122P00001338TravisIH 35PP0016-01-122P00001342TravisIH 35GG0016-01-122P00001345TravisIH 35II0016-01-122P00001346TravisIH 35II0016-01-122P00001348TravisIH 35LL0016-01-122P00001349					
TravisIH 35PP0016-01-122P00001342TravisIH 35GG0016-01-122P00001345TravisIH 35II0016-01-122P00001346TravisIH 35MMM0016-01-122P00001348TravisIH 35LL0016-01-122P00001349					
TravisIH 35GG0016-01-122P00001345TravisIH 35II0016-01-122P00001346TravisIH 35MMM0016-01-122P00001348TravisIH 35LL0016-01-122P00001349					
TravisIH 35II0016-01-122P00001346TravisIH 35MMM0016-01-122P00001348TravisIH 35LL0016-01-122P00001349					
TravisIH 35MMM0016-01-122P00001348TravisIH 35LL0016-01-122P00001349					
Travis IH 35 LL 0016-01-122 P00001349					
1ravis 1H 35 NN 0016-01-122 P00001351					
	1 ravis	111 33	ININ	0010-01-122	P00001351

<u>Eminent Domain</u>

Controlled Acc		ued)			
County	Highw		<u>Exhibit</u>	ROW CSJ No.	Parcel
Travis	IH 35		QQ	0016-01-122	P00001352
Travis	IH 35		BBB	0016-01-122	P00001353
Travis	IH 35		CCC	0016-01-122	P00001354
Travis	IH 35		DDD	0016-01-122	P00001358
Victoria	US 77		HH	2350-01-068	P00059750
Victoria	US 77		JJ	2350-01-068	P00059751
Victoria	US 77		KK	2350-01-068	P00059761
Webb	US 59		EE	0086-14-092	13
Webb	US 59		Ζ	0086-14-093	51
Webb	US 59		А	0086-14-093	53
Wharton	US 59		III	0089-07-163	1
Wharton	US 59		KKK	0089-07-163	3
Wharton	US 59		JJJ	0089-08-104	8
Wharton	US 59		MM	0089-08-104	10
Wharton	US 59		LLL	0089-08-104	13
Wharton	US 59		GGG	0089-08-104	14
Wharton	US 59		HHH	0089-08-104	21
Wharton	US 59		EEE	0089-08-104	29
Wharton	US 59		FFF	0089-08-104	30
<u>Donations to th</u> <u>Donor</u> Alfonso C. New	_	<u>nent</u> <u>Dist</u> TRF	<u>County</u> Maverick		ds to design, fabricate, orial highway designation
Bayten Ltd		HOU	Harris	Design and construc deceleration Lane fro Freeway service road Baytown developme	om eastbound East d into the Crossings at
Caldwell (SAP DTP, LLC)	BRY	Burleson	-	tion of an R-cut on SH 21 perty and FM 60 located in
Cooks Point Hwy21, LLC		BRY	Burleson	-	tion of a left turn lane on r's property located in
Five Eighteen Real Estate, LL	LC	HOU	Galveston	from eastbound FM	tion of a deceleration lane 518 into the 2.63-Acre ment in League City.

Donations to the Department (continued)						
<u>Donor</u> Forestar Group Inc.	<u>Dist</u> AUS	<u>County</u> Travis	Donation Description Design and funds sufficient to cover the state's cost to construct a hooded left turn lane, a culvert, and cable barrier modification to the existing grassy median on eastbound US 290 from Old Kimbro Road to FM 1100 in Manor.			
Forestar (USA) Real Estate Group Inc.	HOU	Montgomery	Design and construction of a street tie-in to connect to the south side of FM 2090 to serve the Splendora Crossing development in Montgomery County.			
Formosa Plastics Corporation, Texas	YKM	Calhoun Jackson	Fixed amount of funds to design and construct two additional through lanes along with turning lanes for public use on FM 1593, from SH 35 to 3.6 miles north of SH 35 in Calhoun and Jackson Counties.			
Gram Vikas Partners, Inc.	SAT	Comal	Design and construction of overhead flashing beacons and left and right turn lanes at the new subdivision intersections of Neumanns Way and Canyon Loop in Comal County.			
Lennar Homes of Texas Land and Construction, Ltd.	SAT	Bexar	Design and construction of a traffic signal and turn lanes on SH 211 and Ladera Hills in San Antonio.			
LGI Homes- Texas, LLC	SAT	Medina	Design and construction of a left turn lane along FM 1957 to provide for safe left turn movements into the proposed development in Medina County.			
MA Durango Farms, LLC	AUS	Williamson	Design and construction of intersection improvements to include 1) right turn lane; 2) left turn lane; 3) sidewalk construction; and 4) traffic signal at FM 1660 and Mager Lane in Hutto.			
Masonwood Lockhart 1, LLC	AUS	Caldwell	Design and construction of deceleration lanes on SH 142 from Borchert Loop to Richland Drive in Lockhart.			
Melissa Ranch Apartments, Ltd.	SAT	Bexar	Design and construction for a deceleration lane along a section of US 90 at Pue Road as off-site improvements for the Melissa Ranch development in San Antonio.			

Donations to the Depart			
<u>Donor</u> Nash FM 529, LLC	<u>Dist</u> HOU	<u>County</u> Harris	Donation Description Design and construction of 1) an eastbound left turn lane, westbound right turn lane, and a traffic signal on FM 529 at Elyson Exchange Way, 2) a westbound right turn lane on FM 529 at Elyson Square Way, and 3) an eastbound right turn lane on FM 529 at southbound SH 99 Frontage Road in the Elyson Development in Harris County.
Nash FM 529, LLC	HOU	Harris	Design and construction of 1) an eastbound right turn lane and a traffic signal on FM 529 at Elyson Boulevard, 2) a westbound right turn lane, and eastbound and westbound left turn lanes on FM 529 at Porter Road, and 3) a westbound right turn lane and eastbound left turn lane on FM 529 at Elyson Village Road in the Elyson Development in Harris County.
NB Dean 32, LLC	SAT	Guadalupe	Design and construction right and left turn lanes for the new Jaro north and south subdivision entrances on FM 758 in Guadalupe County.
Pulte Homes of Texas, L.P.	HOU	Fort Bend	Design and construction of a traffic signal, left turn lane from northbound FM 359 and a right turn lane from southbound FM 359 into the Del Webb Fulshear development in Fulshear.
Richmond RR LLC	HOU	Brazoria	Design and construction of a left turn lane from southbound Cullen Boulevard into the future commercial development in Pearland.
Ridgeland Hills, Ltd.	HOU	Montgomery	Design and construction of two traffic signals at Longstreet Road and I-45 frontage road (northbound and southbound) and a right turn lane from southbound I-45 into the Ridgeland Hills development in Willis.
Rodajo, Inc.	WAC	McLennan	Design and construction of a proposed right turn deceleration lane along the northbound frontage road of I-35 in Waco.

Donations to the Department (continued)						
<u>Donor</u> San Isidro Management, L.C.	<u>Dist</u> LRD	<u>County</u> Webb	Donation Description Funds sufficient to cover the state's cost to construct cost to widen the road for a total of approximately 1,856 square yards to accommodate two driveways and the extension of the turning lane in the vicinity of San Isidro Northeast, Ltd. along US 59 in Laredo.			
Southstar at Mayfair, LLC	SAT	Comal	Design and construction of right turn lanes for two new subdivision entrances known as Ford Trail and Ransom Drive on the northbound frontage road of I 35 and a channelized acceleration lane at Ransom Drive in New Braunfels.			
Tesla, Inc.	AUS	Travis	Fixed amount of funds to cover the state's cost to conduct a Traffic and Revenue Analysis Study for the proposed improvements along SH 130, from north of the Colorado River to FM 969, in Austin.			
William G. Nelson and Steve Nelson	WFS	Cooke	Design and construction of partial removal and rebuilding of concrete and asphalt driving surface, curb of crossover, and median on northbound FM 372 north of O'Neal Street in Gainesville.			
C3 Presents, LLC	AUS	Travis	Revenue generation through the Sponsor a Highway Program. This is a new contract on an existing sign location.			
Northwood Ravin	AUS	Travis	Revenue generation through the Sponsor a Highway Program. This is a contract renewal on an existing sign location.			
El Dorado Chevrolet & Mazda	DAL	Collin	Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.			
Kidd Roofing	DAL	Collin	Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.			
Amber Allen - In Memory of Family Member (Dakota)	DAL	Denton	Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.			

Donations to the Department (continued)						
<u>Donor</u> Exceptional ER	<u>Dist</u> FTW	<u>County</u> Tarrant	<u>Donation Description</u> Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.			
AMCAP Mortgage, LTD.	HOU	Fort Bend	Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.			
J's Pools and Spas, LLC	HOU	Fort Bend	Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.			
AMCAP Mortgage, LTD.	HOU	Harris	Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.			
AMOCO Federal Credit Union	HOU	Harris	Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.			
Shell Federal Credit Union	HOU	Harris	Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.			
Texas Plumbing Supply, Inc.	HOU	Harris	Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.			
Lubbock Electric Co., Inc.	LBB	Lubbock	Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.			
Monaco Residential, LP	ODA	Midland	Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.			
J.D. Collision Express, LLC	SAT	Bexar	Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.			
Rox All Pro Services, LLC dba Rox Roofing & Exteriors	SAT	Bexar	Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.			

Donor	Dist	County
Walker Advertising,	SAT	Bexar
Inc.		

Donation Description

Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.